


Crossing condition register

An indexed route for the spring ground crew.

BIRCH LINE / EXAMPLE ROUTE

Round 01 · spring melt | 3 visible crossings



SPRING ROUTE / SCHEMATIC

READ THE EXAMPLE

Photo convention

Each record pairs IN and OUT views taken from agreed access points. The route map shows illustrative crossing locations and asset IDs.

Register extract

Crossing	Visible condition in example	Suggested follow-up
C-01 · West ditch	Reeds gathered at inlet mouth.	Check after next thaw.
C-02 · Mid-route	Water is ponded at the inlet side.	Ground crew to confirm flow.
C-03 · East ditch	Inlet and outlet openings visible.	Keep reference photos.

Assessment boundary

Dated observations show the exterior at the time of capture. The responsible crew confirms the cause of ponding, internal condition, access and any maintenance work.